



TOYOTA

SAFETY RECALL 21TA06 (Interim Notice 21TB06)

Certain 2018 – 2021 Model Year Tundra
Potential Increased Risk of Vehicle Fire

Frequently Asked Questions

Original Publication Date: September 2, 2021

Q1: What is the condition?

A1: The subject vehicles are equipped with halogen headlamps that allow the circuits for both the high and low beam bulb filaments to be energized at the same time when the high beams are switched on. Under some conditions, if the high beams are repeatedly left on for an extended period while the vehicle is idling or driving at low speed, there is a possibility that the bulb connector could overheat to a level that can result in an increased risk of a fire that can propagate to other parts of the vehicle.

Q1a: Are there any warnings that this condition exists?

A1a: Yes, customer may see smoke from the headlight assembly.

Q1b: Is there anything I can do to avoid this condition before the recall remedy is applied?

A1b: Until the remedy is performed, avoid repeatedly leaving on the high beams while stationary or driving at low speeds for extended periods of time (for example, multiple hours). During these situations, use the low beam if it is safe to do so.

Q2: What is Toyota going to do?

A2: Toyota is currently preparing the remedy. When the remedy is available, Toyota dealers will modify the engine wire harness assembly and inspect the headlight bulb connector, bulb, and headlight assembly. If one or more of these components is found to be damaged due to this overheating condition, the damaged component(s) will be replaced with new ones as needed.

Q3: When will the remedy become available?

A3: At this time, Toyota estimates that the remedy can be available in mid to late 1st quarter 2022

Q4: Which and how many vehicles are covered by this Safety Recall?

A4: There are approximately 158,500 vehicles covered by this Safety Recall.

Model Name	Model Year	Production Period
Tundra	2018-2021	Early June 2017 – Late March 2021

Note: Only Tundra vehicles manufactured in the production period above and equipped with halogen headlamps are involved in this safety recall. Tundra vehicles equipped with LED headlamps are **NOT** involved in this safety recall.

Q4a: Are there any other Lexus/Toyota/Scion vehicles covered by this Safety Recall in the U.S.?

A4a: No, there are no other Lexus/Toyota/Scion vehicles covered by this Safety Recall.

Q5: How does Toyota obtain my mailing information?

A5: Toyota uses an industry provider who works with each state’s Department of Motor Vehicles (DMV) to receive registration or title information, based upon the DMV records. Please make sure your registration or title information is correct.

Q6: *What if I have additional questions or concerns?*

A6: If you have additional questions or concerns, please contact the Toyota Brand Engagement Center at 1-888-270-9371 Monday through Friday, 8:00 am to 8:00 pm, Saturday 9:00 am to 7:00 pm Eastern Time.